








<http://www.qama.fr/charniere-invisible-p69649>



^{*1}When door machining margin is 5 mm.

^{*2}The position of prepared hole for locating changes according to adjustment.